

GEOLOGY OF FORT DUPONT PARK
A Summary of Geologic Factors Affecting Slope Instability and Its Mitigation
By Tony Fleming, Professional Geologist

Introduction

Fort Dupont Park is located in southeast Washington, D.C., about a mile east of the Anacostia River. The major topographic feature is a system of deeply dissected ravines that coalesce into an unnamed tributary to the Anacostia River. The park contains what may be the largest remnant of intact coastal plain forest in the District, and a variety of diverse plant communities are associated with the different micro climates, soils, and moisture regimes that result from the strong topography and varied geologic substrates. The main stream valley in the park has experienced some historical instability of stream banks and valley walls caused primarily by the discharge of urban stormwater from surrounding streets and neighborhoods. Past studies by Federal agencies have reportedly proposed to remediate the stream bank instability by channeling (fluming) the stream and/or installing rip-rap. This report provides a brief overview of park geology and hydrogeology, summarizes the geotechnical factors that appear to be contributing to slope failures, and offers an alternative best management approach that could be employed to address these issues at minimal cost and with little disturbance to the natural community. The observations and conclusions presented herein are based in part on a visit to the park and its surroundings made by the author on May 23, 2004. Regional geologic interpretations are derived from published maps and reports, including Carr (1950); Cooke and Cloos (1951), Cooke (1952), Johnston (1964), McCartan (1989), and the author's professional geologic experience in the D.C. area (e.g., Fleming and others, 1994). Geotechnical information and observations with immediate relevance to the topic at hand can be found in Froelich and others (1980), Obermeier (1984), Obermeier and Langer (1986), O'Connor (1989), Pomeroy (1987), and Withington (1964).

Geology

Fort Dupont Park is located in the deeply dissected terrain along the inner edge of the Atlantic Coastal Plain. The formations found in and near the park range in age from early Cretaceous to Pliocene, and their distribution is well shown by Carr (1950). Most of the sediments exposed in the park belong to the Potomac Group, which is exceptionally well exposed at numerous places along the main stream valley. The oldest unit is the lower Cretaceous Patuxent Formation, which crops out at elevations less than ~125 feet. Here, it is composed chiefly of cross-bedded, quartzose, medium and coarse sand that locally contains a few percent of fine quartz pebbles. Coarse gravel and cobbles were observed as a lag at the bases of a few prominent channel fills, but are largely lacking. The sand is commonly quite oxidized and contains a few localized lenses of light-colored silty clay. Unconformably overlying the Patuxent is a sequence of variegated, maroon, and gray clay, silty clay, and sandy clay with irregular zones of sand, muddy sand, and gravelly sand. Granular sediment constitutes no more than 25% of the section of clay exposed in the park, and the great majority of the unit is very stiff, fractured clay and silty clay with abundant iron-rich zones. Carr (1950) showed this unit as the Raritan Formation, but more recent interpretations (e.g., Cooke, 1952) assign it to the Arundel Clay. The prominent maroon color and the abundance of iron ore are characteristic of the Arundel in the D.C. area (e.g., Cooke, 1952), hence the clay unit exposed at the park likely belongs to the Arundel. The Arundel underlies the

upper reaches of the ravine system, generally at elevations above ~125 feet; it appears to be about 60-70 feet thick in the park. The Miocene age Calvert Formation caps some of the uplands in the park, but is poorly exposed; a few small exposures along the trail near Ridge Road are of golden silty sand, fine sand, and dark sandy silt. The Calvert Formation appears to lie entirely above any of the ravines in the park. Pliocene age river gravel caps the highest ridges south and east of the park. It is composed of medium and coarse pebbles of quartz and sandstone in a deeply weathered orange loam. A thin veneer of colluvial quartz and sandstone pebbles on the upper parts of some hillsides is the only evidence of this unit observed in the park.

Stream Morphology

Uplands in this area are strongly dissected, and streams occupy deep ravines. There is some 200 feet of total relief in the park and well over 100 feet of local elevation differential between the valley bottoms and adjacent ridgetops at most locations. Longitudinal stream profiles in this region are out of equilibrium with base level, and are still adjusting to changes in sea level that occurred during and subsequent to the Pleistocene glaciation. The sharp downcutting that results from this response commonly accentuates differences between geologic formations in terms of their resistance to erosion.

Most ravines in the park are characterized by two distinct segments:

- 1) a broad, U-shaped segment in the downstream reaches, formed in sand of the Patuxent Formation. This lower segment has a uniform, low to moderate stream gradient and a relatively broad floodplain flanked by steep, stable slopes. This segment is dominantly one of stable sediment transport, in which sediment (mainly sand and gravel) derived from upstream is temporarily stored in active point bars and on adjacent floodplains on its way downstream; and
- 2) a narrow, V-shaped upstream segment, formed in Arundel Clay. The upper segment has a consistently steep stream gradient with abundant nick points (small cascades) formed on more resistant beds of gravel and iron-cemented sediment. The floodplain ranges from very narrow to nonexistent; commonly, the streams in this segment are deeply entrenched and actively downcutting in narrow flume-like channels, a process that has been significantly accelerated in the main stream valley by urban stormwater discharge. The upper segment is dominantly one of erosion and active downcutting; there are few point bars and little floodplain storage of sediment in this segment. It is in this segment that the slope failures and accelerated streambank erosion are largely found.

Slope Failures and Streambank Erosion

All of the significant¹ slope failures and streambank undermining observed in the park are found in the upper segment, and all of these are restricted to the main ravine closest to Ridge Road. Typical failures are very small (<10 cubic meters) and involve undermining of stream banks during high water events and subsequent collapse of the bank by sliding into the stream. Common scenarios include rotational slumps² where the toe of the valley wall has been removed by stream erosion, and planar failures of intact blocks of clay along prominent, slope-parallel

¹ "Significant" is defined as being of a noticeably greater rate and/or scale than normal geologic processes.

² Rotational slumps are very common in Potomac Group clays, and are most often triggered when the toeslope is removed. See O'Connor (1989) and Obermeier (1984) for examples.

fracture planes. Both kinds of features generally occur at or near bends (cut banks) in the stream, where the mechanical force of the water is focused, and in both instances, layers of sand beneath the clay appear to increase the potential for slope failures.

Possibly a dozen prominent¹ examples of slope failures of this magnitude, and a number of smaller ones, were observed along the upper segment of the main ravine. None were seen in the lower segment of the main ravine, nor in any other ravine. The main ravine receives a considerable amount of stormwater discharge at its head whereas the other ravines do not. In the upper reaches of the main ravine, the unnaturally large flows created by the stormwater have caused severe downcutting of the channel, commonly leaving near-vertical, unstable banks of clay as much as 10 feet high flanking a gully-like channel. This situation is susceptible to streambank undermining during high flows, which are constantly removing the toe of the slope, creating instability and rotational slumping. Evidence of the erosive force of these flows can be seen in the form of meter-scale chunks of concrete, iron bars, and other heavy objects that have been transported downstream during extreme discharge events. Prominent trim lines, typically several feet above the low-water stage, are visible throughout this segment. Abundant ground water issues from the stream banks in this segment, typically emanating from fractures in clay (which are heavily oxidized as compared to the clay matrix) and from more permeable beds of sand or sandy clay. Zones of ground-water seepage are commonly marked by nodules, crusts, and slabs of iron silicates and iron hydroxide, deposited in response to the redox change that occurs as the ground water discharges to the surface. These iron ores are considerably harder than the surrounding sediment, and the larger zones typically form small ledges in the stream channel and protuberances from the stream banks.

Ground water likely plays an important, though not primary, role in the slope failures. Where a more permeable, saturated sand layer underlies the base of a clay bank, high pore pressures can develop in the sediment above. High pore pressures can wedge blocks of clay loose along slope-parallel fractures (see Sterrett and Edil, 1982); this process probably occurs mainly in the spring and during prolonged wet periods, and appears to be secondary to rotational slumping as a cause of slope failure at Fort Dupont.

Remedial Measures

Using major stream-channel alterations in an attempt to slow slope failures would be an expensive approach to a relatively mild problem, and would be of dubious benefit. Slope failures and streambank collapse are not widespread in Fort Dupont Park. Instead, they are localized in scattered places in the upper segment of the main ravine. The current situation is not posing a threat to safety or property, so it is not clear what the benefit of artificial streambank stabilization would be. Similar, and commonly much worse, situations exist in most of the urban watersheds in the metro area, nearly all of which receive point- and non-point-source stormwater discharge. Some erosion of streambanks is a natural and necessary geological process; attempts to completely eliminate it will ultimately have both expected and unexpected consequences elsewhere in the system. For example, fluming and/or rip-rapping the upper reach of the stream channel will shut off the flow of sediment

¹ Not all of the slope failures are active. Some occurred in the distant past and have largely stabilized by regrowth of protective vegetation and by migration of the stream channel away from their toes.

from the upper segment to the lower segment, thereby causing significant downcutting in the lower segment as the channel bottom there becomes starved for sediment. This will in turn cause a marked nick point to develop at the outlet of the altered channel, which will ultimately undermine the structure itself as the nick point inevitably migrates upstream. Aside from the aesthetic impacts, which are considerable, artificial stream bank stabilization would devastate the very resources the park is intended to protect. Channel straightening and installation of rip rap or a concrete flume would permanently destroy the aquatic ecosystem in the stream, cause lasting damage to the riparian corridor, and cause massive sedimentation downstream during the construction phase, which will require removal of substantial amounts of stabilizing vegetation along the streambank and adjacent areas. Moreover, the upper segment is remote and inaccessible. It is not clear how the heavy equipment needed to implement these measures would access the segment, short of cutting a new road along the ravine, which would necessitate extensive removal of the toes of steep slopes, thereby exacerbating both the extent and possibly the magnitude of slope failures⁴.

The root cause of the current slope/streambank issues is point discharge of stormwater at the head of the main ravine, causing more streamflow than the narrow channel morphology is naturally adjusted to. The result is accelerated downcutting of the channel to accommodate the excess flow. This conclusion is self evident: no other ravine segments exhibit such behavior, because they receive little, if any stormwater discharge. Therefore, if any attempt is made to address the situation, the solution should focus on controlling the stormwater discharge. A simple solution that would be far less expensive and would avoid all of the above problems would be to direct the stormwater to a series of infiltration galleries along the upper edges of the park. These could be shallow (3 feet deep or less) linear trenches or ponds excavated into the sandy Calvert Fm sediment and designed to allow storm water to percolate into the soil. Ecological disturbance would be minimal since most of the outer edges of the park have been disturbed in the past and contain immature forest and a number of exotic species. This approach is not novel: basins and other facilities for the retention and infiltration of storm water are part and parcel of the best management practices commonly prescribed for new residential and commercial developments in the District and in surrounding jurisdictions. An even more direct approach is to address some of the stormwater at its source—namely the hundreds of downspouts that currently channel vast quantities of water from roofs in the watershed directly into the storm-sewer system, and thence into the park's main ravine. Infiltration galleries, dry wells, and similar small-scale in-situ measures to retain storm water where it falls are becoming increasingly more common in the U.S. and elsewhere. It is worth noting that the developed uplands around the park are largely situated on the Calvert Formation and upland river terraces—formations rich in gravel and sand—materials whose relatively high permeabilities are ideally suited to such indigenous solutions.

About the author: Tony Fleming grew up in the District of Columbia near Rock Creek Park, and has studied various aspects of local geology for 3 decades. He is the author of the modern geological map of the Washington West Quadrangle, and several published and unpublished papers on local geology.

⁴ According to the District of Columbia Soil Survey (Smith, 1976), the dominant soils on Potomac Group clays are unstable when disturbed: "Cuts or excavations... are difficult to stabilize and the clay frequently slides, slumps, or flows down the surface of the cuts onto roads or other areas below".

References

- Carr, M.S., 1950. The District of Columbia: its rocks and their history. U.S. Geological Survey Bulletin 967.
- Cooke, C. W., and Cloos, E., 1951. Geologic Map of Prince George's County, Maryland, and the District of Columbia. Scale 1:62,500. Maryland Geological Survey.
- Cooke, C. W., 1952. Sedimentary deposits of Prince George's County and the District of Columbia, *in* Geology and water resources of Prince George's County, Maryland. Maryland Geological Survey Bulletin 10, p. 1-53.
- Fleming, A.H., Drake, A.A., Jr., and McCartan, Lucy, 1994. Geologic Map of the Washington West Quadrangle, District of Columbia, Montgomery County, Maryland, and Arlington County, Virginia. U.S. Geological Survey Geologic Quadrangle Map GQ-1748. Scale 1:24,000.
- Froelich, A.J., Hack, J. T., and Otton E.G., 1980. Geologic and hydrologic reports for land-use planning in the Baltimore- Washington urban area. U.S. Geological Survey Circular 806.
- Johnston, P.M., 1964. Geology and ground-water resources of Washington, D.C. and vicinity. U.S. Geological Survey Water Supply Paper 1776.
- McCartan, Lucy, 1989. Atlantic coastal plain sedimentation and basement tectonics southeast of Washington, D.C. American Geophysical Union Guidebook T214, Washington, D.C.
- Obermeier, S.F., ed., 1984. Engineering geology and design of slopes for Cretaceous Potomac deposits in Fairfax County, Virginia and vicinity. U.S. Geological Survey Bulletin 1556.
- Obermeier, S.F., and Langer, W.H., 1986. Relationships between geology and engineering characteristics of soils and weathered rocks of Fairfax County, Virginia. U.S. Geological Survey Professional Paper 1344.
- O'Connor, J. V., 1989. Engineering geology of Washington, D.C. American Geophysical Union Guidebook T234, Washington, D.C.
- Pomeroy, J.S., 1987. Landslide susceptibility and processes in the Maryland coastal plain, *in* Schultz, A.P., and Southworth, C.S., eds., Landslides of eastern North America. U.S. Geological Survey Circular 1008, p. 5-9.
- Smith, H., 1976. Soil Survey of the District of Columbia. U.S.D.A. Soil Conservation Service.
- Sterrett, R.J., and Edil, T. B., 1982. Groundwater flow systems and stability of slope. Groundwater, v. 20(1), p. 5-14.
- Withington, C.F., 1964. Joints in clay and their relation to slope failure at Greenbelt, Maryland. U.S. Geological Survey Open-File Report.

SUGGESTED FUTURE RESEARCH

Fort Dupont Park

1. The Potomac Group sediments exposed at the park are poorly constrained as to formational status. This could probably be resolved by some additional field observations along with a few hours of research at the Maryland Geological Survey library. Significance: there is quite a bit of useful published literature on slope stability issues associated with the Potomac Group, but it is often formation specific because the type of clay (e.g., the proportion of high shrink-swell montmorillonite) and associated geotechnical characteristics vary by formation.
2. Detailed mapping of stormwater outfalls at the park. Significance: I am assuming that only the main ravine near Ridge Road receives major discharges, but I did not reconnoiter the heads of any other ravines. I base my statements in the report on obvious morphological differences (i.e. lack of erosion in other ravines), topographic maps, and what I was told by individuals familiar with the park.
3. Prepare detailed descriptions of exposures in the park. Significance: The exposures are good in their own right, and systematic documentation of the geology is needed if it would ever be necessary to present the findings of this report to an administrative hearing or court.
4. Prepare a large-scale geologic map of the park, especially in the areas of observed slope failures and streambank erosion. Significance: there appears to be an obvious relationship between geologic unit and slope failures, it needs to be documented. This could also provide the basis for demonstrating that construction of an access road needed to make artificial stream channel alterations would be enormously more destructive than what exists now.
5. Prepare detailed descriptions, surveys, and photo documentation of slope failures and streambank erosion. Develop photographic documentation comparing the morphology and degree of erosion/slope instability in different ravines in the park, to document the case that slope failures are related to the magnitude of stormwater discharges. Significance: see #4, plus relationship to storm water discharges and accelerated downcutting of stream channel associated with them.
6. Obtain detailed topographic coverage of the park to use as a base map. The National Capital Planning Commission at one time had 1:2400 (1" = 200') coverage of the entire region available as a series of blue line prints. In the past, I used some of these sheets for projects in the NW quadrant of the city. Each sheet shows all planimetric features (roads, structures, streams, etc) as well as 5-foot topographic contours. It would be worth investigating whether this coverage is still available, for Fort Dupont and possibly other areas of interest.